


CORNER RECORD

Agency Index BK 23, PG 60Document Number 20210001

City of _____ County of _____ Placer _____, California

Brief Legal Description EAST CORNER COMMON TO LOTS 14/15 of O MAPS 87

CORNER TYPE

Government Corner ☐ Control ☐
Meander ☐ Property ☒
Rancho ☐ Other ☐

Date of Survey January 23, 2021

COORDINATES (Optional)

N. _____ E. _____

Elevation _____

Units ☒ Metric ☐ U.S. Survey Foot ☐

Horizontal Datum _____

Zone _____ Epoch Date _____

Vertical Datum _____

☐ Complies with Public Resources Code §§8801-8819☐ Complies with Public Resources Code §§8890-8902

Section 20 T. 13 N. R. 8E. MDM

PLS Act Ref.: ☒ 8765(d) ☐ 8771 ☐ 8773 ☐ Other:

Corner/
Monument: ☐ Left as found ☐ Established ☐ Rebuilt ☐ Pre-Construction
☐ Found and tagged ☒ Reestablished ☐ Referenced ☐ Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

☐ See sheet #2 for description(s):

Reestablished northeasterly property corner of Lot 14 per found monuments as shown on O Maps 87.

Set 5/8" threaded rod tagged LS8114.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on January 23, 2021Signed [Signature] P.L.S. or R.C.E. No. 8114

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MARCH 22, 2021and examined and filed MARCH 24, 2021Signed [Signature] P.L.S. or R.C.E. No. 8373Title Deputy Co. Surveyor

County Surveyor's Comment

